

SPENCER J. COX

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA Division Director

Minerals Inspection Report

04/21/2014

Reviewed

PB13

Mine Name: Pine Ridge	Permit Number:	S/037/0120	Mine Status:	Reclaimed
Operator Name: Energy Fuels Resources (USA)	Inspection Date:	04/15/2014	Permit Fees:	No Fee Req.
Inspector(s): M. Bradley	Inspection Time:	08:00a	Bond Amount:	\$1,200
Attendee(s): See below	Weather:	Clr. Pt. Cldy, cool	Bond Escalation:	N/A
Inspection Purpose: Routine inspection			Prior Inspection:	08/27/2013

Conclusions and Recommendations

Attendees: Joel Nowak, USFS; Andrea Reither, EFR; Stephen Downs, EFR; Race Fisher, EFR; Todd Eldredge, EFR.

Report Date:

Inspected site to observe progress of revegetation for final bond release. Grading is considered complete. It was too early to see this year's crop of vegetation, looked similar to last year. All parties agreed that another year was needed to determine revegetation success, and a visit at a later date on the calendar was necessary to allow vegetation to recover from winter.

	Elements of Inspection	Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds		
2.	Public Safety (shafts, adits, trash, signs, highwalls)	$\overline{\boxtimes}$	
	Adit remains covered and unlocatable		
3.	Protection of Drainages/Erosion Control		
	No evidence of any erosion problems		
4.	Deleterious Material		
5.	Roads (maintenance, surfacing, dust control, safety)		
	Access road remains blocked with several rows of large boulders		
6.	Reclamation		
	Grading is complete, waiting on revegetation		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)		
	See comment 2 above		
8.	Soils		
9.	Revegetation		
	Too early in season for recovery of vegetation from winter or annual crop co	ming up.	
10.	Other 1		

Inspector's Signature:

CC: Joel Nowak, USFS (joelnowak@fs.fed.us)
Andrea Reither, EFR (areither@energyfuels.com)

Frank Filas, EFR (ffilas@energyfuels.com)

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M037-SanJuan/S0370120-PineRidge/inspections/INSP-04152014.pdf



Mine: S/037/0120 Inspected: 04/15/2014



Overview of mine location



View toward approximate location of portal



View toward east from near center of pad



View from slope of backfilled portal toward west

